



## Public Health

### Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)

### RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME <b>COLTON COMMUNITY CENTER</b>		DATE <b>5/1/2015</b>	REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>7/31/2015</b>
LOCATION <b>670 COLTON AV, COLTON, CA 92324</b>			INSPECTOR <b>John Babalola</b>	
MAILING ADDRESS <b>650 LA CADENA DR, COLTON CA 92324</b>			IDENTIFIER: Splash Pad	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 001 - INSPECTION - ROUTINE	
TIME IN <b>11:50 AM</b>	TIME OUT <b>12:45 PM</b>	FACILITY ID <b>FA0001922</b>	RELATED ID <b>PR0034206</b>	PE <b>3621</b>
			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
			ACTION: 01 - NO FURTHER ACTION REQUIRED	



### RECREATIONAL HEALTH - Public Pool - Additional Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**98**
**SCORE**

<b>Ideal</b>
<b>In Compliance</b>
<b>Not in Compliance</b>



temperature (°F)	No Data
observed flow (gpm)	0
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

### 36K448 Equipment - Flow Meter

**POINTS**
**2**

Compliance Date: Not Specified

Not In Compliance

Violation Reference - CCR - 3125B

**Inspector Comments:** Repair/replace the non-functional flow meter.

**Violation Description:** A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

### Overall Inspection Comments

No summary comments have been made for this inspection.

### Signature(s) of Acknowledgement

NAME: Brandon Parra

TITLE: Recreation Coordinator

Total # of Images: 0